

Visual - VT Testreport

Reportno.: **kopi**
Rev. no./Date: xx16
Testdate: xx
Page: 1 of 2

Client: Straumen Bil AS Inspection of: Volvo ECR88 Order no #0001:	Supervisor: NAVN Drawing no.: N/A	Test Site: xxxx Project Name: Volvo ECR88	Client Orderno.: N/A Project No.: Test 01A
---	---	---	---

Object / Geometry / Joint: Beam Weld Process: Not Stated Ref. Standard: NS-EN ISO 17637:2011	Dimensions (mm): 6 Surface Condition: Grinded Acc. Criterias: EN ISO 5817 Level B	Material: C/S Heat Treatment: No Post Weld HT Procedure: PRO TEST	Groove: N/A WPS: Not Stated Test Extent: 100%
--	---	---	---

Test Equipment:
Flashlight,

Comments, additional information:
VT was carried out on areas that have been straightened after damage.

Result:

Accepted

Repairs marked on:

Object

Sketch

Pictures, drawing, sketches:

Operator: Navn	Cert. No.: xxxx-N2-V	Date: xx.xx.xxxx
--------------------------	--------------------------------	----------------------------

Signature & Stamp:

For Client:

Visual - VT Testreport

Reportno.: **xxx** Rev.
no./Date:
Testdate: dato
Page: 2 of 2

Pictures, drawing, sketches:



Operator:
navnt

Cert. No.:
xxxx-N2-V

Date:
xx.xx.xxxx

Signature & Stamp:

For Client: